

MODIFICATION INSTRUCTIONS for the **Kodak MINILOADER 2000P** **Service Code: 3479**

Modification No. 11 Type 1 Selective

Purpose: To improve the transfer of film between the PROCESSOR INTERFACE and the PROCESSOR. This Mod decreases the number of C-B7 error codes. This Mod is revised to install a FOAM STRIP to prevent film fog.



Important

Qualified service personnel must install this modification.

Service Effects: None

Special Requirements: None

Serial Numbers: All

Installation Time: 1.0 hour

Special Tools: None

Parts Status: Available from Service Parts Management.

Parts Requirements: See Page 2.



HEALTH IMAGING

Confidential
Restricted Information
© Eastman Kodak Company, 2003

PLEASE NOTE

The information contained herein is based on the experience and knowledge relating to the subject matter gained by Eastman Kodak Company prior to publication.

No patent license is granted by this information.

Eastman Kodak Company reserves the right to change this information without notice, and makes no warranty, express or implied, with respect to this information. Kodak shall not be liable for any loss or damage, including consequential or special damages, resulting from any use of this information, even if loss or damage is caused by Kodak's negligence or other fault.




This equipment includes parts and assemblies sensitive to damage from electrostatic discharge. Use caution to prevent damage during all service procedures.

MODIFICATION KIT H9315106 includes:

Part No.	Description	Quantity
---	ENTRY FILM GUIDE	1
---	UPPER FILM GUIDE	1
---	LOWER FILM GUIDE	1
6F2029	FOAM STRIP	1
7C8275	Modification Reimbursement Card	1
MA3479-11	MODIFICATION INSTRUCTIONS	1


Installing the Modification



Warning

Dangerous Voltage

- [1] De-energize the PROCESSOR.
- [2] Open the 2 LATCHES.
- [3] Move the MINILOADER for access to the PROCESSOR.




- [4] Remove the LIGHT BAFFLE.



- [5] Remove the ENTRANCE DETECTOR AY.

MODIFICATION INSTRUCTIONS, TYPE 1



[6] Remove:


- 4 SCREWS
- PROCESSOR INTERFACE



[7] Disconnect the 2 CONNECTORS.

[8] Remove from the REAR PANEL:


- 4 SCREWS
- 4 WASHERS



Warning

Do not damage the 2 wires.


[9] Move the REAR PANEL from the PROCESSOR with the 2 wires connected.




[10] Loosen the MOUNTING STUD.

[11] Remove:

- 2 SCREWS
- WASHER
- SPACER



[12] Install the new ENTRY FILM GUIDE into the 2 holes of the left and right side PLATES.




[13] Install:

- SPACER
- WASHER
- 2 SCREWS

[14] Tighten the MOUNTING STUD.


MODIFICATION INSTRUCTIONS, TYPE 1



[15] Cut the FOAM to allow the removal of the UPPER FILM GUIDE from the PROCESSOR INTERFACE.


[16] Remove:

- 4 SCREWS
- UPPER FILM GUIDE



[17] Remove:

- 2 SCREWS
- 2 WASHERS
- LOWER FILM GUIDE



Important

Prevent the SLEEVE PLATE from touching the new LOWER FILM GUIDE.

[18] Hold the SLEEVE PLATE up.

[19] Install:




- new LOWER FILM GUIDE
- 2 WASHERS
- 2 SCREWS

[20] Install:

- new UPPER FILM GUIDE
- 4 SCREWS

 **Note**

The new UPPER FILM GUIDE has no FOAM.



[22] Are the 4 CAGED NUTS installed on the inside of the PROCESSOR FRAME?

Yes	No
Continue with Step 23 .	<ol style="list-style-type: none">Remove the 4 CAGED NUTS.Install the 4 CAGED NUTS on the inside of the PROCESSOR FRAME.Continue with Step 23.

[23] Install the REAR PANEL.



REAR PANEL




[24] Install to the REAR PANEL:

- 4 WASHERS
- 4 SCREWS

[25] Connect the 2 CONNECTORS.

[26] Install:


- PROCESSOR INTERFACE
- 4 SCREWS




[27] Install the ENTRANCE DETECTOR AY.



[28] Install the LIGHT BAFFLE.





[29] Move the MINILOADER to close the PROCESSOR.

[30] Close the 2 LATCHES.

Completing the Modification

- [1] Energize the PROCESSOR.
- [2] Operate the MINILOADER using the customer's film.
- [3] Check:
 - that the MINILOADER operates correctly with 18 x 24 cm and 24 x 30 cm size films.
 - that the processed film has no scratches or artifacts.
- [4] Circle "11" on the MODIFICATION LABEL on the MINILOADER.
- [5] Record the information for feedback:

K-number	Service Code	Serial No.	Activity Code	Installation Time	Part No.
	3479		M11		H9315106

Publication History

Publication Date	Publication No.	ECO No.	Changed Pages	File Name	Notes
21MAY03	MA3479-11	54339	---	ma3479_11.fm	New Publication
14NOV03	MA3479-11	2665-104	1, 2, 4, 7, 8, 9, and 11	ma3479_11.fm	Revised

Kodak is a trademark.

Printed in U.S.A. • ma3479_11.fm

EASTMAN KODAK COMPANY
Rochester, NY 14650

HEALTH IMAGING